## NOS Parts Still Available

Description

3735157 L.H. head pipe-exhaust

Part

Number

0/00/07	rieda pipe exilaust
3735164	R.H. head pipe-exhaust
3762440	Part of tail pipe (need 2 ea.)
3752556	Part of tail pipe - extension
3736269	L.H. door weather strip
3736270	R.H. door weather strip
3754505	Radiator hose - lower
3931600	Intake manifold gasket
3192095	Shock - front (need 2 ea.)
3730111	Door molding L.H. Lower
3730112	Door molding R.H. Upper
3730113	Door molding R.H. Lower
3730114	Door molding L.H. Upper
3740253	Weather strip - windshield glass
3762525	L.H. top weatherstrip
3762526	R.H. top weatherstrip
3762529	Top weatherstrip
3814213	Weatherstrip topcover
Parts I fo	ound that are listed for 1956 that are for
1960 to 1	962:
3770284	Top of fan shroud
3192962	Rear shock - non-spiral
3733572	Molding lower R.S. front fender
3839808	Screw, side-view mirror
3725377	Window crank handle w/chrome knob
4156542	Door handle, R.S.
4156543	Door handle L.S.
445504	Screw assy includes
	starwasher - top latches
3725755	Bezel, use with 3725754 emblem,
Marian at Therese	2 oeg 'd per car
3751130	Seal, 3 spd shift boot (also for
07000 10	PG and 4 spd?)
3728940	Floor plate, transmission
3742212	Fuel injection emblem, trunk & front
2767507	fenders, '57 only
3767507	Crossed flag emblem, front fender



All screws used in Corvette to hold various items were slotted. Any questions?


## '53 - '55 TOP FILLER FLAPS

By Roy Braatz

Most owners of '53 to '55 Corvettes have had problems with air getting into the cockpit area while driving with the soft top up and side windows installed. Other than a poor fit, which is understandable, many owners have gotten the top and windows to fit tight and proper but still complain of air hitting them in the neck when the window vent is opened.

Reproduction tops have now nearly duplicated the original down to the date codes, but have overlooked one little fact that a GM driver discovered early on when test driving the Corvette. "Filler flaps" that were used on all '53-'55 tops located between the lower bottom rear mohair seal and the bottom side snap hold down.

This is a poor picture taken from a GM service manual but shows the filler flap stitched to the top material. Having your local upholstery shop add them will cure the problem of cold air running up your neck and making the top more original.





Master brake cap 5300880, Cast Iron '53-'61