SACE TECHNICAL PANEL

Technical advisors have three duties: (1) answer questions from the general membership regarding problems they are experiencing with their car; (2) record the questions and answers and transmit them to the Straight Talk editor for publication; and (3) provide assistance in the preparation of a technical guide book.

Every request for assistance will require the requestor and the advisor to jointly complete the form. The advisor will send it to the Straight Talk editor.

Any member wishing to make use of this service may contact the advisors listed. If you write, please use the form and include a stamped, self-addressed envelope. If you phone, have the information ready for the top half of the form before you call.

Be considerate of the time zone differences, and place your call so it is received between 8:00 and 9:00 P.M. for the advisor. If you want the advisor to call you back, be prepared to accept the collect toll.

Technical Advisors are:

P.O. Box 1080

Roy Braatz

Soquel, CA 95073 (408) 475-4442

14521 Bears End Drive

Nevada City, CA 95959 (916) 265-59447

recnnical Advisors are:	
Steve Solokoff (53-55)	John Kocsis (56-57)
4524 Baltimore Avenue	Rt. 2, Box 281-C
Philadelphia, PA 19143	Athens, PA 18810
(215) 382-6366	(717) 888-7418
Mike McCagh (53-55)	Ron Smith (56-57)
1715 Frederick Street	1582 Surrey Drive
Cumberland, MD 21502	Santa Rosa, CA 95401
(301) 777-0089	(707) 579-1341
Dwight Farmer (58-60)	David Bartush (56-57)
5232 Foxboro Landing	6560 Red Maple Lane
Virginia Beach, VA 23464	Birmingham, MI 48010
(804) 495-0154	(313) 642-3522
Jim Lockwood (58-60)	Jeff Reed (56-57)
P.O. Box 691	239 W. Main Street
Mountain View, CA 94042	Mesa, AZ 85201
(408) 723 -2775	(602) 833-1012
Brooks Cooper	Joe Trybulec (56-57)
12647 Fantasia Drive	470 Albert Drive
Herndon, VA 22070	Florissant, MO 63031
(703) 471-5776	(314) 831-7841
Joe Calcagno (61-62)	Larry Richter (56-57)

Update on Engine Paint

I'm not sure if you got a copy of the data on the '53-'55 6-cylinder engine paint.

P.O. Box 328

Coos Bay, OR 97420

Bill Eldridge (58-60)

561 Olele Pt. Road Port Ludlow, WA 98365

(206) 437-2120

(503) 269-1427

I have a 16 May 1989 letter from DuPont Automotive Products in Troy, Michigan, stating the color was 73119 Deluxe, Engine Enamel Blue. Mr. Brian Dotterer of G.M. confirmed it was the only blue used on '53-'54 Corvette engines (I assume on '55 6-cylinder also).

Here is the formula for 1 quart:

1	White	457 gr.
15	Blue	741 gr.
2	Black	880 gr.
14	H. Red	892 gr.
VD	5450 Dryer	928 gr.

Now, the only problem I have with this is that the formula card has "Released: February 28, 1955" on it. So I'm writing to DuPont again to see if they have an explanation. The color number is correct. My DuPont jobber's formula for 73119 still matches the 1955 formula. My only concern is of the possibility that between '53 and '55, the formula was changed but they kept the same formula number. This seems unlikely, but who knows.

Note that there is no yellow in the formula. For the paint to appear greenish there would have to be yellow mixed with the blue. The theory is that as the blue ages with heat, it turns green. If so, a factory fresh or restoration paint job should not be green! (Is Rhoner green).

I'll let you know what I find out from DuPont.

We all know the Chevy engine blue in rattle cans is not correct. I suspected, however, that G.M. blue might be this 73119. I bought a can of G.M. Blue to compare it with 73119 and found G.M. Blue is still too dark. It looks like 73119 is closer to the Chrysler Blue which is a light blue. Or, half-way between G.M. and Chrysler..

Here's an odd one for you. The window bag twist fasteners in my trunk were painted black. I stripped the paint off and found they were made of brass. The screw stud and core is steel, but the metal casing is brass, not chrome or stainless.

P.S. Here is a list of some parts still in the Chevy system. Publishing a complete list for the club would be a great project.

NUMBER	DESCRIPTION	PRICE	
1358938 3834956 3985944 398594? 3829376 358501 459023 471162 6264903 5660233	U JOINT "U" BOLTS WHEELS 15 X 5 RIVETED FRONT BRAKE DRUM REAR BRAKE DRUM LUG BOLTS LUG NUTS LOWER A-ARM BUMPERS FRONT WHEEL GREASE CAPS STEERING "O" RING UPPER COLUMN BEARING W/CABLE STABILIZER SHAFT BUSHINGS STABILIZER SHAFT LINK & SHOCK BUSHINGS	.86 48.35 49.67 49.67 .96 .44 1.95 1.75 .18	EA
599430 6270752	STABILIZER SHAFT BUSHINGS STABILIZER SHAFT LINK & SHOCK BUSHINGS	.96 .34	
319295 3192962 3756540 1427894	BUSHINGS FRONT SHOCKS REAR SHOCKS FRONT SPRINGS REAR SPRING FRONT EYE BUSHINGS 1.5" I.D. AIR OUTLET HOSE TACH & SPEEDO CABLE GROMMET REAR AXLE REBOUND STRAPS WIPER BLADES OUTSIDE MIRROR TO BRACKET SCREW DOOR LOCK HANDLE KNOB	16.10 16.10 45.05 1.39	EA. EA. EA. EA.

I've no idea which of these other than the shocks and rebound straps are not exact replacements. I believe Noland said the wheels are "55 passenger style, not '53-'54 'Vette. Do you know if the defroster hose (air outlet hose) is correct?

You've advised about weatherstripping. Do you know of other dealer stock parts which will work for my '54?